




OO270X69P




OO274X60U





OO170X40S



OO180X60G




OOxxxX60A




	L	
OO200X60A	200	
OO230X60A	230	
OO250X60A	250	
OO260X60A	260	
OO295X60A	295	
OO600X60A	600	
OO670X60A	670	

OO120X80F



OO230X120F



ОТКОСЫ

	a	b	L _{max}	M
0080X40	80	40	700	
00115X50	115	50	800	
00130X45	130	45	860	
00130X50	130	50	700	
00140X50	140	50	800	
00150X45	150	45	900	
00150X50	150	50	900	
00160X50	160	50	800	
00180X50	180	50	670	
00190X50	190	50	550	
00200X45	200	45	800	
00214X50	214	50	600	
00220X50	220	50	740	
00220X69	220	69	600	
00235X50	235	50	670	
00240X50	240	50	850	
00240X60	240	60	900	
00250X50	250	50	770	
00250X55	250	55	355	
00250X60	250	60	600	
00250X70	250	70	700	
00280X60	280	60	800	
00295X60	295	60	640	
00350X50	350	50	680	
00350X70	350	70	800	
00370X50	370	50	600	
00390X60	390	60	830	
00400X50	400	50	780	
00500X60	500	60	600	
00580X60	580	60	700	

Откосы прямые

